

ARDISAM, INC PRODUCT EVALUATION

PRODUCT EVALUATED

CASTLE MODEL SERENITY

EVALUATION PROPERTY

ASTM E2515, ASTM E2779, CSA B415.1

REPORT NUMBER

104591879MID-001

ORIGINAL ISSUE DATE

03/08/21

LAST REVISED DATE


ORIGINAL

PAGES

11

DOCUMENT CONTROL NUMBER

SFT-BC-OP-19H © 2017 INTERTEK





Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001

Date: 03/08/21

PRODUCT EVALUATION RENDERED TO:					
Company Name:	Ardisam, Inc.				
Address:	1690 Elm Street				
	Cumberland, WI 54829				
	Seth Bailey				
Tel:	715-822-2415 ext. 130				
Email:	sbailey@ardisam.com				

Table of Contents

ARD	ISAM, INC	1
Р	RODUCT EVALUATION	1
Tab	le of Contents	2
1	Introduction	3
2	Product and Assembly Description	3
	.1. Product Description:	
	Reference Documents	
4	Evaluation Method	3
5	Conclusion	4
6	APPENDIX	5
7	LAST PAGE & REVISION SUMMARY	. 11

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample(s) tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.



Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001

Date: 03/08/21

1 Introduction

Intertek Testing Services NA Inc. (Intertek) is conducting a product evaluation for Ardisam, Inc., on model Serenity pellet fuel room heater, to evaluate changes to audit drawings and review for 5-year EPA certification update. The evaluation is being conducted to determine if the listing report review will maintain compliance with ASTM E2515-17 - Standard Test Method for Determination of Particulate Matter Emissions Collected by a Dilution Tunnel, ASTM E2779-17 - Standard Test Method for Determining Particulate Matter Emissions from Pellet Heaters, and CSA B415.1-10 - Performance Testing of Solid-Fuel-Burning Heating Appliances.

2 Product and Assembly Description

2.1. Product Description:

The model Serenity Pellet Fuel Room Heater is constructed of sheet steel. The outer dimensions are 20.25-inches deep, 34-inches high, and 18.25-inches wide. The unit has a door located on the front with a viewing glass.

3 Reference Documents

As part of this evaluation, Intertek has directly or indirectly used the following referenced documents:

- ASTM E2515-17
- ASTM E2779-17
- CSA B415.1-10
- Spec ID No. 36796
- Intertek Testing Report No. 102366578MID-002R1 dated December 22, 2015, revised March 5, 2021

4 Evaluation Method

Ardisam, Inc. requested a review of the emissions report (Spec ID #36796) to be able to reapply for another 5-year certification with the U.S. EPA. In addition to this review, Ardisam revised three drawings to better clarify the vent connector and back panel of model Serenity.

The revised vent connector drawing is showing a reduction of 5 mm to the outer diameter of the collar. The material thickness and length remain the same.

The revised back panel is showing a reduction of 15 mm of the total height of the panel. All ports and vents in the panel remain the same.



Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001

Date: 03/08/21

S Conclusion

Intertek has conducted this product evaluation for Ardisam, Inc., on model Serenity pellet fuel room heater, to evaluate changes to audit drawings and review for 5-year EPA certification update. The evaluation was conducted to determine if the listing report review will maintain compliance with ASTM E2515-17 - Standard Test Method for Determination of Particulate Matter Emissions Collected by a Dilution Tunnel, ASTM E2779-17 - Standard Test Method for Determining Particulate Matter Emissions from Pellet Heaters, and CSA B415.1-10 - Performance Testing of Solid-Fuel-Burning Heating Appliances.

Based on the information contained and referenced herein, it is Intertek's professional judgment based on sound engineering principles that the following is true:

- The vent connector utilizes a baffle plate that is welded to the vent tube, which creates restriction in the venting. A reduction of 5 mm in diameter for the vent connector will not have any effect on the safety or performance of the model Serenity.
- The reduction of 15 mm in height for the back panel of the model Serenity has been deemed compliant. All of the ports and vents remain the same.
- No other changes have been made since the Serenity was originally tested in 2016; therefore, this model remains compliant with the referenced standards.

INTERTEK TESTING SERVICES NA LTD.

Reported by:

Brian Ziegler

Technical Team Leader - Hearth

Reviewed by:

Ken Slater

Associate Engineer - Hearth

Version: 12/15/17 Page 4 of 11 SFT-BC-OP-19h




Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001

Date: 03/08/21

6 APPENDIX




Original vent connector 1



Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001




Original Vent Connector 2



Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001




Original back panel



Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001




Updated Vent connector 1



Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001




Updated Vent Connector 2



Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001



Updated Back Panel



Telephone: 608-836-4400 Facsimile: 608-831-9279 www.intertek.com/building

PRODUCT EVALUATION FOR ARDISAM, INC

Report No.: 104591879MID-001

Date: 03/08/21

7 LAST PAGE & REVISION SUMMARY

DATE	SUMMARY	REPORTER	REVIEWER
March 8, 2021	Original	Brian Ziegler	Ken Slater

Version: 12/15/17 Page 11 of 11 SFT-BC-OP-19h